

## IGNITION COIL

Order No.	REPLACES
<b>SD-3001</b> 	<b>VOLKSWAGEN</b> 330 905 115A <b>BOSCH</b> 0 221 502 007 0 221 502 008
<b>SD-3002</b> 	<b>FTM-063 GT</b> <b>SUZUKI</b> <b>DAIHATSU</b> <b>TOYOTA</b> 33410-8-120
<b>SD-3003</b> 	<b>DAIHATSU</b> 90048-52026, 90048-52096 <b>DIAMOND</b> F-076, F-614 <b>YEC</b> YGC-501 <b>CHARADE</b> S/X 1.0 CX 1.3 16V
<b>SD-3004</b> 	<b>ALFA ROMEO</b> 60805420 60809492 <b>BERU</b> ZS 283 <b>CHAMPION</b> BAE 800B <b>FIAT</b> 49 543 562 46 548 037 46790073 7 626 232 7 672 018 <b>MARELLI</b> 060 708038010 607 080 38 BAE 800 AK BAE 800B BAE 800DK